

Unregistered Software Call: 760.450.2026 or

2003-115 El Camino Real Oceanside CA 92054 760.650.1255 IdentifyReport@gamil.com



Report # / I.D : Inspection Date : Client Name : Property Address : Dell06132015 June 13 2015 Time : 1:30 Donald Dell 1121 Any Street La Jolla, Ca 92038

Buyers Agent :

Donald Smith Re-Max Associates 707 Escondido Ave Thousand Oaks CA. 860-643-3700 Sellers Agent :

Tom Wiington Re-Max Associates 707 Escondido Ave Thousand Oaks CA. 860-643-3700

Re Inspected On 06/21/2015 All Previous Defects Confirmed

Inspection General Description

Foundation

Due to the floor being covered, the only part of the foundation visible to me to inspect is the stem wall around the perimeter of the house. There are some cracks that appear to be common in size and type.

Exterior

Monitor the wood around the windows, doors and roof. Ensure the wood is always well sealed and protected against weathering. Monitor the wood trim around the windows and doors. Ensure the wood is always well caulked and sealed to the side of the house not to allow for moisture intrusion in behind the wood. Monitor the bottom of door thresholds and ensure they are caulked and sealed to the foundation not to allow for moisture intrusion. Routinely check for any damage to the walls of the house that could allow for moisture intrusion and do the necessary repairs to the walls.

Grading

Monitor the drainage around the property to ensure that water is draining away from the foundation as quick as possible. Do not allow water to drain to or pond next to the foundation. Common cracks noticed in the perimeter wall. I recommend you keep the wood on the side gate sealed and protected from weathering and deterioration.

Roof

Routine inspections recommended and maintenance to all roof systems to a house to ensure integrity of the roof. Wind driven rain can cause roof leaks which can happen regardless of the visible condition of the roof at the time of the inspection.

Plumbing

Be aware that shut off valves/supply valves are not tested as leaks may occur that would necessitate immediate repairs. I recommend replacing all gate valves with quarter turn valves as preventative maintenance.

Attic

I will enter an attic space whenever possible. I will utilize storage boards if provided and the work platform in front of the air handler to inspect the attic space. Not all of the attic may be visible to me. The inspection of the attic is therefore limited.

Bathrooms

I recommend you monitor all caulk and grout lines around all wet areas to ensure a watertight seal at all times. Routinely check caulk and grout lines and do general maintenance and repairs especially in the shower. Routinely check under sinks for possible leaks from drain lines, supply valves and sink stopper connections to the drain lines.

Heating and Cooling System(s)

Heating systems cannot be properly tested in the summer and conversely, AC units cannot be properly tested in the winter time as operating these systems could cause damage to the units. Recommend routine maintenance and service to the heating and cooling systems of the house which will also extend the useful life of these units.

Laundry

I recommend routinely cleaning the dryer vent professionally which will ensure optimum performance of the dryer and proper venting.

The following items are outside the scope of my inspection and may or may not be present in the house at the time of the inspection: Washers, dryers, refrigerators, water softeners, reverse osmosis, central vacuum, surround sound systems, home theater systems, any audio/video systems that may convey, security systems, intercom systems and remote controlled window blinds.

THE INSPECTION REPORT LEGEND & INTRODUCTION PAGE

THE BRACKETED NUMBERS ARE DEFINED AS FOLLOWS:

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of infestation / deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done

with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

Note: Most of the time the deficiency will just be noted. If it is a Possible Safety Hazard it will be noted. I always recommend a licensed professional in the related field do examinations & or repairs.

Anytime these statements: Appears to be mold or mildew type substance, mold/mildew is visible are used, mold may be a health & or safety issue & need further inspection & or remediating by a specialist.

The term " Satisfactory/Functional " or " Appears Satisfactory/Functional " Is used to identify an item or component that was found to be functionally usable at the time of the Property Inspection. Normal wear & tear is not noted.

THE PURPOSE OF THE PROPERTY INSPECTION

The Property Inspection is a Non-Invasive physical examination designed to identify material defects in the systems / structures / components of the building as they exist at the time of The Property Inspection. The Property Inspection is limited to those systems / structures / components that are present & accessible. Components / Systems shall be operated with normal user controls only & as conditions permit. The Inspection Report may contain recommendations for evaluations / testing / repairs / upgrades / inquiries or comments about an item or condition that should be brought to the Client(s) attention.

THE PROPERTY INSPECTION OUTLINE

The Client(s) are invited & encouraged to accompany the Property Inspector during The Property Inspection process. When completed, The Property Inspection will be reviewed on site, assuming the Client(s) are present. The Report identifies separate areas, such as Electrical / Plumbing / Heating / Roof / Bathrooms, etc. If The Client(s) have any Questions / Comments, Please Call The Inspector As Soon As Possible.

The Inspector works solely for the Client(s), not the Agents or Sellers.

The Inspector has no vested interest in whether or not The Property purchase is completed.

The Inspector does not perform repairs / referrals for repairs, to Prevent a Conflict of Interest.

The Inspection Report is not a Warranty or Guarantee of any kind. If a Home Warranty is not provided

by the Sellers, Agents or Others. The Client(s) are is strongly advised to obtain one.

The use of the Inspection Report is authorized for the sole use of The Client(s) identified on The Contract.

The Inspector / Inspection Company has no contractual obligations or fiduciary responsibility to any third

parties / agents / future purchasers or any other persons that may come into possession of The Inspection Report.

By initialing below the Client(s) or Client(s) Real Estate Agent / Representative, acknowledges reading & understanding the Inspection Report Legend / The Purpose of the Inspection / The Inspection Outline / The Report Summary and The Inspection Report Contract, including The Standards of Practice.

Client Initials.	Date.	Client Initials.	Date.
------------------	-------	------------------	-------

Initials of Client(s) Real Estate Agent / Representative only if client(s) are not able to attend the inspection.

Initials of Client(s) Real Estate Agent / Representative. _____ Date. _____ Date. _____

Unregistered Software Call: 760.450.2026 or 760.650.1255

IdentifyReport@gamil.com

2003-115 El Camino Real

Oceanside CA 92054

760.650.1255

Report #: Dell06132015 Client: Donald Dell

Property: 1121 Any Street La Jolla, Ca 92038

Your Inspector's Name, Inspector

Inspection Date: June 13, 2015

FOUNDATION / STRUCTURE:

l = Inspec	ted NI = Not Ins	pected NP =	Not Present	D = Defect	S = Safity Issue	
Slab:	🗌 I 🛛 NI 🗌 NP	DDS	Basement:	🗌 I 🗌 NI	□NP □D □S	
Raised:	🗌 I 🛛 NI 🗌 NP	🗆 D 🔲 S	Other:	🗌 I 🗌 NI	□NP □D □S	
Structure:	🛛 I 🗌 NI 🗌 NP	D DS	Mobile / Mod	ule: 🗌 I 🗌 NI	NP 🗌 D 🗌 S	

NOTICE: The visible portions of the foundation / structure were observed to determine their condition at the time of inspection. The condition of foundations / slabs / subfloors not visible due to carpet / floor coverings cannot be determined. The wall surfaces or design configuration of the structure often prevents access to visually verify the presence or condition of anchor bolts. If any foundation damage / deterioration / infestation is reported the client is strongly advised to obtain the services of a qualified licensed structural engineer / Geotechnical engineer / termite / pest inspector & consider any recommendations for repair / replacement / treatment prior to the close of escrow. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

FOUNDATION TYPE	Concrete / Wood 2 Story
UNDER FLOOR ACCESS	Not Applicabile
UNDER FLOOR VENTILATION	Not Applicable
STRUCTURE TYPE	Town House
FLOOR FRAMING	Not Visible
VAPOR RETARDER	Not Visible
INSULATION	Not Visible
BEAMS & PIERS	Wood Beams
SUB FLOOR	Not Visible

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

Property Owners Association / Park Management Statement

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell

Property: 1121 Any Street La Jolla, Ca 92038

IdentifyReport@gamil.com 760.650.1255 Your Inspector's Name , Inspector

2003-115 El Camino Real

Oceanside CA 92054

Inspection Date: June 13, 2015

EXTERIOR:

I	= Inspected	N	I = Not I	nspect	ed	NP = Not Present	D = Defect	S = Safi	ty Issue	
Grade:	۱ 🛛	🗌 NI	🗌 NP	🗌 D	S	Sidewalk:	🛛 I 🗌 NI		D 🗌 S	
Surface:		🛛 NI	🗌 NP	🗌 D	S	Stairs:	🗌 I 🗌 NI		D 🗌 S	
Trim:		🛛 NI	🗌 NP	🗌 D	🗌 S	Electrical:	🗌 I 🗌 NI		D 🗌 S	
Windows	: 🛛 🛛 I	🗌 NI	🗌 NP	🗌 D	🗌 S	Fences / Gates:	🗌 I 🗌 NI		D 🗌 S	
Doors / Ja	ams: 🛛 🔀 I	🗌 NI	🗌 NP	🗌 D	S	Retaining Wall:	🗌 I 🗌 NI		D 🗌 S	
Driveway	: 🛛 I	🗌 NI		🗌 D	S	Porch / Patio:	🗆 I 🗌 NI		D 🗌 S	

NOTICE: The visible portions of the exterior surfaces / trim were observed to determine their condition at the time of inspection. Destructive testing of exterior wood surfaces / trim to determine the presence of any deterioration / infestation is beyond the scope of this report. Damaged / infested areas reported should be repaired / treated by appropriate specialist. The routine maintenance of door & window frames is required to prevent damage / leaks. The client is strongly advised to obtain & review the termite / pest report & consider any recommendations for repair / treatment of the property prior to the close of escrow. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

EXTERIOR SURFACES	Primarily Stucco & Wood
TRIM	Primarily Wood Needs Repairs
SURFACE GRADE	Acceptable
DRIVEWAYS / SIDEWALKS	Ashphalt
EXTERIOR DOORS	Type: Sliding Glass & Wood Hose Bibs In Front & Rear
WINDOWS MAT./PLANT LIFE	Material Is: Aluminum & Single Pane Glass
PATIOS / PORCHES	Concrete Patio('s)
FENCES & GATES	Not Applicable
SOIL CONDITION:	Dry , Generally Flat
LANDSCAPE SPRINKLER SYSTEM	Not Part Of This Inspection

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

Exterior Electrical:

Inoperable / Broken Light found at: Rear Patio Bedroom Next to sliding Doors

See Photo # 13, 14

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

Exterior Surface:

Stucco surface is cracked / damaged at several areas. See Photo # 15, 16, 1, 18 See Photo # 15, 16, 1, 18 See Property Owners Association / Park Management Statement

Exterior Enter Enter:

Moisture noted on Exterior brick Walk way, Recommend redirecting water for greenery. See Photo # 19,20,21,22,23,24

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.

(6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

EXTERIOR PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 IdentifyReport@gamil.com

Your Inspector's Name , Inspector



Exterior Light Damaged



Exterior Light Damaged



Exterior Stucco Damage



Exterior Stucco Damage



Exterior Stucco Damage



Exterior Stucco Damage

EXTERIOR PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255


Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 IdentifyReport@gamil.com

Your Inspector's Name, Inspector




Front Entry Exterior Moisture Noted Recommend to Redirect Watering



Front Entry Exterior Moisture Noted Recommend to Redirect Watering




Front Entry Exterior Moisture Noted Recommend to Redirect Watering



Front Entry Exterior Moisture Noted Recommend to Redirect Watering



Front Entry Exterior Moisture Noted Recommend to Redirect Watering



Front Entry Exterior Moisture Noted Recommend to Redirect Watering

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Donald Dell Client: Property: 1121 Any Street La Jolla, Ca 92038 2003-115 El Camino Real Oceanside CA 92054

IdentifyReport@gamil.com 760.650.1255

Inspection Date: June 13, 2015

Your Inspector's Name, Inspector

ROOF / ATTIC:

l = Insp	ected NI = Not Inspect	ed NP = Not Present	D = Defect	S = Safity Issue	
Main Roof:	🗌 I 🖾 NI 🗌 NP 🗌 D	S Gutters:	🗌 I 🗌 NI	□NP □D □S	
2nd Roof:	🗌 I 🖾 NI 🗌 NP 🗌 D	S Ventilation:	🗌 I 🔲 NI	□NP □D □S	
Flashing:	🗌 I 🖾 NI 🗌 NP 🗌 D	S Attic Electric:	🗌 I 🗌 NI	🛛 NP 🗌 D 🔲 S	
Attic Framing:	🗌 I 🛛 NI 🗌 NP 🗌 D	S Garage Roof:	🛛 I 🗌 NI	🗌 NP 🗌 D 🔲 S	
Insulation:	🗌 I 🖾 NI 🗌 NP 🗌 D	S Garage Attic:	🛛 I 🗌 NI	□NP □D □S	

NOTICE: The visible portions of the roof / roof penetrations / flashings & attic space were observed to determine their condition at the time of inspection. Roofs will only be inspected by walking on their surfaces if reasonably accessible / if doing so will not cause any damage to the roof / endanger the inspector. Reporting if a roof has an active leak is not possible unless the leak is observed at the time of inspection. Reporting remaining life expectancy / predicting future roof leaks is beyond the scope of this report. If damaged / deteriorated / missing areas are reported the client is advised to obtain the services of a qualified licensed roofing contractor for further evaluation prior to the close of escrow. The testing of gutters / down spouts / underground drains is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

tile

ROOF MATERIAL/VALLYS	Primarily Gable Primarily Conctere/Clay
ROOF SHEATHING	Material Is: Unable To Identify
ATTIC / ROOF FRAMING	Unable To Determine
ATTIC ACCESS & LOCATION	No Access Provided
ATTIC INSULATION	Not Visible
ATTIC VENTILATION	Not Fully Visible
FLASHINGS	
GUTTERS / DOWNSPOUTS	None
SKYLIGHTS/KITCHEN & BATH ROOF	None Present

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

Garage roof is a Flat Roof, seems to be New ... See Property Owners Association / Park Management Statement

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist. (4)
- Recommend upgrading for Health / Safety / Function / Efficiency Enhancement. (5)
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell

Property: 1121 Any Street La Jolla, Ca 92038

Inspection Date: June 13, 2015

Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name, Inspector

2003-115 El Camino Real

CHIMNEY / FIREPLACE:

l = Insp	ected	NI =	= Not Ins	spected	NP = Not Present	D = Defect	S = Safity Issue
Chimney:		🛛 NI	🗌 NP	D DS	Other:		NP 🗌 D 🗌 S
Fireplace:	I	🔀 NI	NP	D DS			

NOTICE: The visible portions of the fireplace / chimney were observed to determine their condition at the time of inspection. Associated mechanical features are tested by operating their normal controls to verify proper function. Reporting on chimney draw / performing a smoke test / ignition of wood / gas / the use of video equipment is beyond the scope of this report. If damaged / deteriorated / inoperable / unsafe items / features are reported the client is advised to obtain the services of a qualified licensed chimney contractor / specialist for further evaluation / testing prior to the close of escrow. Gas logs controlled by a switch / thermostat found shut off / that have shut off pilots will not be tested & pilots will not be lighted. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

CAPS AT ROOF: SPARK SCREEN AT FIREPLACE SPARK SCREEN AT STOVE DIRECT VENT GAS FIREPLACE WOOD BURNING FIREPLACE Not Visible Fireplace Located In: Living Room Yes Present N/a Gas Fireplace Only No Gap Device Not Present

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

FIREPLACE

See Photo # 37. Need to install a gap device.

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

CHIMNEY & FIREPLACE PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 <u>IdentifyReport@gamil.com</u>

Your Inspector's Name , Inspector



Living Room Fireplace

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038

IdentifyReport@gamil.com 760.650.1255

Inspection Date: June 13, 2015

Your Inspector's Name , Inspector

2003-115 El Camino Real

Oceanside CA 92054

INTERIOR ROOMS:

	I = Inspected	NI = Not I	nspected	NP = Not Present	D = Defect	S = Safity Issue	
Electrical	: 🛛 🛛 I	🗆 NI 🗌 NP	D DS	Windows:	🛛 I 🗌 NI	□NP □D □S	
Floors:	X I	🗌 NI 🗌 NP	🗌 D 🔲 S	Screens:	🛛 I 🗌 NI	□NP □D □S	
Walls:	🛛 I	🗆 NI 🗌 NP	🗌 D 🔲 S	Cabinets / Draws:	🛛 I 🗌 NI	□NP □D □S	
Ceiling:	🛛 I	🗆 NI 🗌 NP	🗌 D 🔲 S	Closet Doors:	🛛 I 🗌 NI	□NP □D □S	
Doors:	X I	□NI □NP	D DS	Stairs / Railings:	🛛 I 🗌 NI	□NP □D □S	

NOTICE: The visible portions of the interior rooms were observed to determine their condition at the time of inspection. A comparative sample of the windows / doors / closets / cabinets / outlets / switches / fixtures were observed / tested to determine their condition at the time of inspection. Furniture / clothing will not be moved to test outlets / inspect walls / floors. Duel Pane seal failure will be reported where observed, however, weather / temperature / light changes can make identifying all problems difficult / impossible. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

WALLS / CEILINGS	Drywall / Plaster Walls
FLOORS	Type: Wood, Carpeting & Tile
DOORS	Wood & Glass
WINDOWS & SCREENS	Material Is: Type Is:
STAIRS / RAILINGS	ls: Wood
ELECTRICAL	See Electrical Section
CABINETS / CLOSETS	Wood / Mirrored Closet Doors

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

Entry Hall: Closet has things stored, Doors needs adjusted will not stay Closed See Photo # 49

Entry Hall: Danger: Trip Hazard, Hall Entry To Down Stairs See Photo # 51

Entry Hall: Cracks Noted On Wall above Garage Entry Door. See Photo # 57

Entry Hall: Floor Damaged at Bottom of Garage Enter Door. See Photo # 59

Entry Hall: Entry Door Damaged, Molding Damage. See Photo # 60

Master Bedroom: Sliding door hard to open and close and will not Lock. Needs repair/ Replacement. See Photo # 56, 58 Master Bedroom: Sliding Glass Door Will Not Lock Hard to Open or Close See Photo # 55

Bedroom # 2 Bedroom 2: Wall above Sliding doors Needs Repair, See Photo # 52

- Bedroom # 2 Slinging Door Hits Door When Closing See Photo # 55
- Bedroom # 2 Heater Vent, Wall damage See Photo #53
- Bedroom # 2 Moisture Noted at Sliding glass Door. See Photo # 54
- Bedroom # 2 Moisture Noted at Wall. See Photo # 159

Living Room: Noted Added Electric Out Let. See Photos # 157, 158

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #:Dell06132015Client:Donald DellProperty:1121 Any Street La Jolla, Ca 92038Inspection Date:June 13, 2015

2003-115 El Camino Real Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name , Inspector

INTERIOR ROOMS:

Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a qualified licensed contractor / specialty trades person.

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INTERIOR PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255


Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 IdentifyReport@gamil.com

Your Inspector's Name, Inspector



Living Room Wet Bar is Prep For Plumbing



Entry hall Closet Doors will not Stay Closed



Danger: Trip Hazard, Hall Entry To Down Stairs



Bedroom 2: Wall above Sliding doors Needs Repair



Damage Noted at Vent



Moisture Noted in Carpet at slinging Door Bedroom 2

INTERIOR PHOTOS

Inregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015



Bedroom 2 Slinging Door Hits Door When Closing

2003-115 El Camino Real Oceanside CA 92054 760.650.1255 <u>IdentifyReport@gamil.com</u>

Your Inspector's Name , Inspector



Master Bedroom Sliding Glass Door Will Not Lock Hard to Open or Close



Crack at Enter hall Above Garage Entry Door



Slinging Glass Door Bedroom 2



Damaged Floor at Garage Enter Door



Front Door Molding

INTERIOR PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255


Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 <u>IdentifyReport@gamil.com</u>

Your Inspector's Name , Inspector




Right side of Sliding Door Moisture Noted (2)



Right side of Sliding Door Moisture Noted (2)



Ceiling Repaired in Bedroom 1 No Moisture Noted



Ceiling Repaired in Bedroom 1 No Moisture Noted

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name, Inspector

KITCHEN:

NP = Not Present	D = Defect	S = Safity Issue
S Vent & Hood:		
S Electrical:		$\square NP \square D \square S$
S Floors:		
S Walls:		
Ceiling:		
Doors:		
Windows:	🛛 I 🗌 NI	
S Screens:	🛛 I 🗌 NI	
	SVent & Hood:SElectrical:SFloors:SWalls:SCeiling:SDoors:SWindows:	S Vent & Hood: I NI S Electrical: I NI S Floors: I NI S Valls: I NI S Ceiling: I NI S Doors: I NI S Windows: I NI

NOTICE: The visible portions of the kitchen were observed to determine their condition at the time of inspection. Associated built in appliances / fixtures / counters / cabinets / sinks / drains were observed / tested to determine their condition at the time of inspection. Appliances are not checked for temperature calibration / timer function / microwave oven radiation leaks. Testing water filter / purification equipment / instant hot water heating equipment is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

Counters / Cabinets / Drawers	Fridge	Oven
Sinks / Faucets	Ice Maker	Range
Garbage Disposal	Built in microwave	WetBar Sink Plumbing(If PRESENT)
Built In Dishwasher	vent hood	GFCI (If Present)

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below. KITCHEN:

Disposer electric plug needs repair / Replace. Kitchen in Wall Moisture Noted With Moister Probe in Several Areas. See Photo # 62, 63, 64, 65 Cabinet Door Under Sink Damaged See Photo # 65 Damaged Garnet Counter Top at Left of Sink, Missing Quarter Round. See Photo # 68 Gap Noted at Kitchen sink, Needs Calking to prevent Water Damage. See Photo # 67 Floors: Tile is Not Sealed to Floor, May come Loose. See Photo # 66

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

KITCHEN PHOTOS

⁻ Jnregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015

Kitchen View

2003-115 El Camino Real Oceanside CA 92054 760.650.1255 <u>IdentifyReport@gamil.com</u>

Your Inspector's Name , Inspector



Kitchen in Wall Moisture Noted With Moister Probe



Kitchen in Wall Moisture Noted With Moister Probe , Kitchen in Wall Moisture Noted With Moister Probe



Water stain on Kitchen Window Seal and wall



Damage to Kitchen Sink Cabinet



Kitchen Tile Not sealed to Floor

KITCHEN PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 <u>IdentifyReport@gamil.com</u>

Your Inspector's Name, Inspector



Gap at Kitchen and Garnet



Damaged Garnet at next to Kitchen Sink

KITCHEN PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255


Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 IdentifyReport@gamil.com


Your Inspector's Name , Inspector



Kitchen Moisture Noted in Several Areas



Kitchen Moisture Noted in Several Areas



Loose Tile And Moisture Noted

Loose Tile And Moisture Noted

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name , Inspector

BATHROOMS:

	= Inspected	NI = Not I	nspected	NP = Not Present	D = Defect	S = Safity Issue	
Sink: Faucets: Bathtub: Shower: Shower D Toilets: Drains: Bidet: Electrical Fans / Ve	· ⊠ I ⊠ I ⊠ I ⊠ I □ I □ I □ I	NI = Not I. NI NP NI NP	nspected D S D S D S D S D S D S D S D S	NP = Not Present Cabinets: Heaters: Spa Tub: Steam Bath: Floors: Walls: Ceiling: Doors: Windows:	D = Defect	S = Safity Issue NP D S NP D S	
Counterto				Screens:		NP D DS	

NOTICE: The visible portions of the bathrooms were observed to determine their condition at the time of inspection. Associated built in appliances / fixtures / counters / cabinets / sinks / drains were observed / tested to determine their condition at the time of inspection. Verifying the presents / temperature setting of no shock faucets / fixtures / determining if shower pans, tub / shower enclosures are water tight is beyond the scope of this report. Capacity of the water heater to serve the demands of a spa tubs is not reported. Any comments about the bathroom floors, walls, ceilings, doors, windows are located at the interior rooms page. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

Locations: Hall & Master Bathroom

Sinks & Sink Fixtures	Toilets	Counter / Cabinets / Drawers
Bathtubs & Tub Fixtures	Exhaust Fan	Traps / Drains / Supply
Showers & Shower Fixtures	Whirlpool Tub	G. F. C. I. Outlets Provided ?????

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

Upstairs Bathroom 1/2 Bath. Fan Needs Repaired/Replaced, Makes Lots of Nose. See Photo 76

Master Bathroom

Sinks: Sink drain Pop Up Stopper needs repair / adjustment at one or more locations. See Photo # 73 Danger: Bath Tub Light Not to Code. May Result in Electric Shock See Photo # 74

Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a qualified licensed contractor / specialty trades person.

All Bathroom Sinks, Tubs and Counters Need re-calking. See Photo # 75, 77Upstairs Bathroom

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.

(6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

BATHROOMS PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 IdentifyReport@gamil.com

Your Inspector's Name, Inspector



Master Bathroom Sink




Master Bath Electric Light Not In Code



Both Bathrooms need Re-Calking Around Bath Tub, Sinks and Counters



Entry Hall 1/2 Bath Exhaust Fan needs Repaired/Replaced



Both Bathrooms need Re-Calking Around Bath Tub, Sinks and Counters

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell

Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name , Inspector

PLUMBING:

l = Inspected	d	NI = 1	Not Insp	ected	NP = N	ot Present	D = Defect	t S	= Safity	Issue	
Water Meter:	×ι	🗆 NI	🛛 NP	D	S						
Water Shut Off:	×ι	🗆 NI		🗌 D	S	Hot Water He	eater: 🔀	I 🗌 NI	🗌 NP	🗌 D	S
Hose Bib:	X I	🗆 NI	🗌 NP	🗌 D	S	E / Q Straps:	\boxtimes			D	□s
Supply Line:	X I	🗌 NI	🗌 NP	🗌 D	🔀 S	Presser Temp	Valve:			D	□s
Waste Line:		🗆 NI	🛛 NP	🗌 D	S	Combustion A	Air:			D	□s
Gas Meter:	X I	🗌 NI	🗌 NP	🗌 D	S	Elevation:				D	□s
Solar Water System:	X I	🗌 NI	🗌 NP	🗌 D	S	Pan / Drain:				D	□s
Water Softener:	I I	🗌 NI	🛛 NP	🗌 D	S	Flue Supply:				D	□s
Sprinklers:	X I	🗆 NI	🗌 NP	🗌 D	□s	Other:					□s
Other:	× I			D	S						

NOTICE: The visible portions of the main water line, shutoff valve, water supply lines, drain / waste pipes & gas meter / pipes were observed to determine their condition at the time of inspection. Leaks, damage, corrosion of the plumbing system concealed from view / located underground cannot be reported by a visual inspection. Fixture shutoffs including those serving kitchen, bathrooms, wet bar sinks, laundry, etc. are not tested due to risk of causing a leak requiring immediate repair. Testing of water softeners, water filters, sump pumps as well as the testing of solar systems serving water heaters / pools / spas are beyond the scope of this report. Gas meters found shut off will not be turned on & gas appliances found shut off will not be tested & pilots will not be lighted. Some A B S plastic drain / waste pipe systems have experienced problems. Identifying when or by what company these materials were manufactured is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

WATER METER	Unable To Determine
WATER SHUT OFF VALVE	Not Viewed
WATER SUPPLY LINE	Not Visible For Inspection Water Pressure 62
WATER HEATER BRAND	A.o. Smith- 40 Gallon Gas
FUNCTIONAL WASTE DRAIN	Old Not Tested Water Heater May Be The Original Unit
GAS METER/SHUT OFF LOC.	See Comments Water Heater Located In Garage
WATER HEATER TPR PIPE	Present No Test Pipe Is Copper
WATER & SEWER:	City Water And Sewer
GAS PIPING	Black Iron Not Fully Visible
LAWN SPRINKLER SYSTEM	Outside The Scope Of My Inspection
	Outside The Scope Of My Inspection

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

Water Heater: May be at end of life, Makes popping sound when turned on to test. See Photo # 85 Water Heater: Hot Water Heater Shut off Valve Corroded . See Photo # 86

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.


PLUMBING PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 IdentifyReport@gamil.com

Your Inspector's Name, Inspector



Hot Water Heater Rusted



Hot Water Heater Shut off Valve Corroded

Report #: Dell06132015

Unregistered Software Call: 760.450.2026 or 760.650.1255

2003-115 El Camino Real Oceanside CA 92054

760.650.1255

Client: Donald Dell

Property: 1121 Any Street La Jolla, Ca 92038

IdentifyReport@gamil.com Your Inspector's Name Inspector

Inspection Date: June 13, 2015

ELECTRICAL:

l = Ins	pected	NI = Not	Inspect	ted	NP = Not Present	D = De	efect	S	= Safity	/ Issue	
Main Panel:	🛛 I 🗆 NI		D	S	Ground, Plumbing-	Ground:				D	S
Service:	🛛 I 🗌 NI		D	S	Smoke / Carbon						
Branch Wiring:	🗌 I 🛛 NI	🗌 NP	D	S	Monoxide Dete	ctors: Other:					
G.F.C.I.:	🛛 I 🗌 NI		D	S		oulei.					

NOTICE: The visible portions of the service entrance, grounding system, main / sub panels were observed to determine their condition at the time of inspection. Lights & accessible outlets / switches are checked for basic operation. Smoke detectors will be tested only if accessible & provided with a built in activation button / switch. The function of time clocks is not verified. The location & operation of ground fault circuit protection (G. F. C. I.) will be identified. Light fixtures that have missing or broken bulbs are considered nonfunctioning. Motion sensor / dusk to dawn light fixtures & low voltage yard lights are not tested. Electrical equipment found disconnected / dismantled will not be tested. Determining the adequacy / efficiency of the overall electrical system is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

SERVICE ENTRANCE	Is Underground
MAIN PANEL LOCATION/ BRAND	Closet Brand Is Stab Lok Main
MAIN BREAKER/ CIRCUIT TYPE	Breakers
PANEL RATING AMP/VOLTAGE	120/240 At Max 120 Amps
BRANCH CIRCUIT WIRING	Material Type: Wire Type:
GROUND FAULT DEVICES	Provided In Baths & Kitchen
SMOKE DETECTORS	Bedrooms & Hall
ALUMINUM WIRING VISIBLE	None
MAIN PANEL SERVICE WIRE	Service Wire Is Copper
MAIN SERVICE GROUND	Not Fully Visible
MAIN ELECTRICAL DISCONNECT	Location Main Panel In Closet

Recommendations For Evaluations / Repairs / Upgrades / Inguiries & Comments Noted Below.

Stab Lok Main & Sub panels and circuit breakers manufactured by Federal Pacific are suspected of having design flaws which can allow them to cause shock hazards and fires. We recommend replacement of these panels. Note also that electricians may not work on this equipment, and replacement parts may be difficult to find and expensive. See Photo # 97, 98 Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

Master Bath Light Not To Code. See Photo # 100

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist. (4)
- Recommend upgrading for Health / Safety / Function / Efficiency Enhancement. (5)
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

ELECTRICAL PHOTOS

⁻ Jnregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015


Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015



Main Electric Panel

2003-115 El Camino Real Oceanside CA 92054 760.650.1255 <u>IdentifyReport@gamil.com</u>

Your Inspector's Name, Inspector



Main Electric Panel




Lights In Master Closet



Light In Master Shower Not To Code



Electric Main Panel In Closet , No Hot spots Noted



Electric Main Panel In Closet , No Hot spots Noted

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell

Property: 1121 Any Street La Jolla, Ca 92038

Oceanside CA 92054

2003-115 El Camino Real

IdentifyReport@gamil.com 760.650.1255

Inspection Date: June 13, 2015

Your Inspector's Name , Inspector

HEATING / COOLING:

l = Inspected		NI = Not Inspected			NP = Not Present		D = Defect	S = Safity Issue	
Heating:		🗌 NI		🗌 D	S	Ducting:	🛛 I 🗌 NI	□NP □D □S	
Venting:	🛛 I	🗌 NI		🗌 D	🗌 S	Cooling / AC:	🗌 I 🗌 NI	🛛 NP 🗌 D 🔲 S	
Combustion Air:	🛛 I	🗌 NI		🗌 D	🗌 S	Other:	🗌 I 🔛 NI	🛛 NP 🗌 D 🔲 S	
Thermostat:	N I	🗌 NI		🗌 D	□ S				

NOTICE: The visible portions of the heating / cooling units, associated electrical / gas connections, vents, ducting & filters were observed to determine their condition at the time of inspection. Heating / cooling systems are tested by operating normal controls / thermostats to verify proper function. Checking for cracks / damage to heat exchangers & dismantling the components of heating / cooling systems is beyond the scope of this report. Heating / cooling systems found shut off / that have shut off pilots will not be tested & pilots will not be lighted. Heating / cooling systems are not evaluated for efficiency or adequacy. Thermostats are not checked for calibration / timer functions. Some makes / models of horizontal gas heaters are involved in a safety recall, this determination requires the services of a qualified licensed heating contractor / specialist. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

PRIMARY HEATING SYSTEM	Central Natural Gas
THERMOSTATS / CONTROLS	Located In Lower The Hall
DUCTING	Unable To View
VENTING / COMBUSTION AIR	Metal Vent & Vent Cap & Combustion
AIR FILTERS	Disposible Type
CENTRAL AIR CONDITIONING	

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

Heating: Recommend cleaning/vacuuming furnace. See Photo # !09

Heating: Insufficient combustion air is provided to furnace / utility closet. Increase combustion air by adding vents, trimming bottom of door, or adding a louvered door.

Heating: Heater has a Flex Tub Installed ware a Steel Line Needs to Be to Prevent Gas Leek. See Photo # 110

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

HEATING / AC PHOTOS

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 <u>IdentifyReport@gamil.com</u>

Your Inspector's Name, Inspector



Heater Located in Closet



Gas Line In Properly Installed

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell

Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name, Inspector

GARAGE

I = Inspected		NI = Not Inspected				NP = Not Present	D = Defect	S = Safity Issue		
Slab / Floor:	ΝI	🗌 NI	🛛 NP	🗌 D	□s	Garage Attic:				
Fire Door:	×Ι	🗌 NI	🗌 NP	🗌 D	□s	Ceiling:				
Fire Wall:	×Ι	🗌 NI	🗌 NP	🗌 D	🗌 S	Walls:				
Access Door:		🗌 NI	🗌 NP	🗌 D	🛛 S	Floors:				
Vehicle Door:		🗌 NI	🛛 NP	D	S	Doors:				
Automatic Opener:				D	S	Windows:				
Electrical:	×ι			D	⊔s	Screens:		🛛 NP 🗌 D 🔲 S		
Vents:				D	∐s	Other:		🛛 NP 🗌 D 🔲 S		
Garage Roof:					⊔s					

NOTICE: The visible portions of the garage / carport were observed to determine their condition at the time of inspection. Associated mechanical equipment is tested by operating normal controls to verify proper function. Fire door self closing devices / automatic garage door openers / garage electrical / access doors / windows are checked for proper / safe function. Comments about equipment / appliances located inside the garage / carport i. e. electrical panels / laundry / water heaters / water softeners / heating / cooling equipment / water shut off / yard sprinkler controls / timers etc. will be found on their appropriate pages of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

SLAB / FLOOR	Concrete
FIRE WALL / DOOR	Unable To Determine Fire Rating
WALLS & CEILINGS	Drywall Finished
ACCESS / SIDE DOOR	Doors Locked, Unable To Inspect
VEHICLE DOOR / OPENER	Metal " Tilt Up Style " No Automatic Opener Provided
REMOTE OPENERS	None Visible To Test
TYPE OF GARAGE	Attached
GARAGE ELECTRICAL	Acceptable Garage Heater

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

Garage Wall: Stain on Wall. Cuttently Dry, Unable to determine Ware it Came From. See Photo # 121

Garage: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

Unregistered Software Call: 760.450.2026 or 760.650.1255

GARAGE PHOTOS

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 Inspection Date: June 13, 2015 2003-115 El Camino Real Oceanside CA 92054 760.650.1255 IdentifyReport@gamil.com

Your Inspector's Name , Inspector



Water Stain

Unregistered Software Call: 760.450.2026 or 760.650.1255

Report #: Dell06132015

Client: Donald Dell Property: 1121 Any Street La Jolla, Ca 92038 2003-115 El Camino Real Oceanside CA 92054

Inspection Date: June 13, 2015

IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name, Inspector

LAUNDRY:

I = Inspected	NI = Not Inspected	NP = Not Present	D = Defect	S = Safity Issue
Counter Tops:ICabinets:IWasher:IDryer & Vents:IElectrical:ISinks:IDrains:IExhaust Fan:I	NI NP D S NI NP D S	Ceiling: Walls: Floors: Doors: Windows: Screens: Other:	 □ I □ NI 	NP □ D □ S NP □ D □ S

NOTICE: The visible portions of the laundry room / area were observed to determine their condition at the time of inspection. The washer hook ups / drain connections / fixtures / counters / cabinets / sinks / drains / outlets / switches were observed / tested to determine their condition at the time of inspection. Testing the washer / dryer by running the equipment through a wash / dry cycle is beyond the scope of this report. However, washer will be tested to ensure it fills & drain water, & dryer will be tested to ensure it heats up. Washing & Drying capabilities will not be tested. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

Traps / Drains / Supply Washer **Dryer Hook Up Is**

Laundry Electrical Washer Hook Up Is Electric **Current Dryer Is Gas**

Grounded Outlet Provided

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.

No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- Recommend upgrading for Health / Safety / Function / Efficiency Enhancement. (5)

(6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

Report #: Dell06132015 Unregistered Software Call: 760.450.2026 or 760.650.1255									
Client: Donald De	əll						2003-11	5 El Camino Real	
Property: 1121 Any S	Street La	a Jolla, Ca 92	2038				Oce	anside CA 92054	
Inspection Date: June	e 13, 20 ⁻	15			<u>lde</u>	entifyReport@	<u>gamil.com</u>	760.650.1255	
						Your li	nspector's	Name, Inspector	
l = Inspecte	ed l	NI = Not Insp	ected	NP =	Not Present D	= Defect	S = Safity Issue		
FOUNDATION	/ STRI	UCTURE		Inspe	cted : OYes	🔵 No			
Slab:	🗆 I 🛛	🛾 NI 🗌 NP	🗌 D	S	Basement:	🗌 I 🗌 NI	NP [D S	
Raised:		🛾 NI 🗌 NP	🗌 D	S	Mobile / Module:	🗌 I 🗌 NI	🛛 NP 🛛	D S	
Structure:	⊠ ∎ [NI NP	🗌 D	S	Other:	🗌 I 🗌 NI	🛛 NP 🗌	D S	
EXTERIOR:				Inspe	cted : 🔵 Yes	O No			
Grade:	X I [NI NP	🗌 D	S	Sidewalk:	🛛 I 🗌 NI		D S	
Surface:		🛾 NI 🗆 NP	🗌 D	S	Stairs:	🗌 I 🗌 NI		D S	
Trim:	🗆 I 🛛	🛾 NI 🗆 NP	🗌 D	S	Electrical:	🗌 I 🗌 NI		D S	
Windows:	X I [NI 🗆 NP	🗌 D	🗌 S	Fences / Gates:	🗌 I 🗌 NI		D S	
Doors / Jams:	X I [NI 🗆 NP	🗌 D	🗌 S	Retaining Wall:	🗌 I 🗌 NI		D S	
Driveway:	🛛 I 🗆	NI NP	🗌 D	S	Porch / Patio:	🗌 I 🗌 NI	□ NP □	D S	
ROOF / ATTIC:				Inspe	cted: OYes	🔵 No			
Main Roof:			🗌 D	□s	Gutters:			D S	
2nd Roof:			D	□s	Ventilation:			D S	
Flashing:			🗌 D	□s	Attic Electric:		NP [D S	
Attic Framing:			🗌 D	□s	Garage Roof:	🛛 I 🗌 NI		D S	
Insulation:	🗆 I 🗵	NI 🗆 NP	🗌 D	S	Garage Attic:	🗌 I 🗌 NI	NP [D S	
CHIMNEY / FIR	EPLA	CE:		Inspe	cted : OYes	<mark>O</mark> No			
Chimney:			D	□s	Other:				
Fireplace:			🗌 D	□s					
INTERIOR ROC	OMS:			Inspe	cted : OYes	O No			
Electrical:			D	□s	Windows:				
Floors:				□s	Screens:				
Walls:			D	□s	Cabinets / Draws:				
Ceiling:			D	□s	Closet Doors:				
Doors:			D	□s	Stairs / Railings:			D S	
KITCHEN:				Inspe	cted : 🔵 Yes	O No			
Sink:			D	□s			_	_	
Faucets:				□s	Vent & Hood:			D S	
Countertops:				□s	Electrical:			D S	
Cabinets:				□s	Floors:			D S	
Drawers:				□s	Walls:			D S	
Drains & Traps:				□s	Ceiling:			D S	
Disposers:				□s	Doors:			D S	
Dishwasher:				□s	Windows:				
Stove & Oven:			D	□s	Screens:	🛛 I 🗌 NI		D S	
	_	_							

I = Inspected

NI = Not Inspected

NP = Not Present

D = Defect

Report #: Dell061320	015	Unregistered Software Call: 760.450.2026 or 760.650.1255										
Client: Donald De)					2003-115 El Camino Real						
Property: 1121 Any Street La Jolla, Ca 92038 Oceanside CA 92054												
Inspection Date: June 13, 2015 IdentifyReport@gamil.com 760.650.1255												
Your Inspector's Name , Inspector												
l = Inspecte	d NI = N	lot Inspected	NP	= Not Present D	= Defect	S = Safity Issue						
BATHROOMS:			Inspe	ected : 🔵 Yes	O No							
Sink:	🛛 I 🗌 NI	NP D	□s	Cabinets:								
Faucets:	🛛 I 🗌 NI	□NP □D	S	Heaters:								
Bathtub:	🛛 I 🗌 NI	🗌 NP 🗌 D	S	Spa Tub:		NP D S						
Shower:	🛛 I 🗌 NI	🗌 NP 🗌 D	🛛 S	Spartub. Steam Bath:								
Shower Door:	🗆 I 🗌 NI	🛛 NP 🗌 D	S	Floors:								
Toilets:	🛛 I 🗌 NI	🗌 NP 🗌 D	🗌 S	Walls:		NP D S						
Drains:	🛛 I 🗌 NI	🗌 NP 🗌 D	🗌 S	Ceiling:								
Bidet:	🗆 I 🗌 NI	🛛 NP 🗌 D	🗌 S	Doors:								
Electrical:	🛛 I 🗌 NI	🗌 NP 🗌 D	🗌 S	Windows:		□ NP □ D □ S ⊠ NP □ D □ S						
Fans / Vents:	🛛 I 🗌 NI	🗌 NP 🗌 D	🗌 S	Screens:								
Countertops:	🛛 I 🗌 NI	🗌 NP 🗌 D	S	Screens.		NP LD LS						
PLUMBING:			Inspe	ected : 🔵 Yes	O No							
Water Meter:			□s	Но	t Water He	ater:						
Water Shut Off:	🛛 I 🗌 NI	□NP □D	□s	Damage / Leaks:		□NP □D □S						
Hose Bib:	🛛 I 🗌 NI	□NP □D	□s	E / Q Straps:								
Supply Line:	🛛 I 🗌 NI	□NP □D	□s i	Presser Temp Valve:								
Waste Line:	🗆 I 🛛 NI	□NP □D	S	Venting								
Gas Meter:	🗆 I 🛛 NI	□NP □D	□s	Combustion Air:	🛛 I 🗌 NI	□NP □D □S						
Solar Water System:	🗆 I 🗆 NI	NP D	□s	Elevation:	🛛 I 🗌 NI	□NP □D □S						
Water Softener:	🗆 I 🗌 NI	NP 🗌 D	S	Pan / Drain:	🗆 I 🔲 NI	🛛 NP 🗌 D 🔲 S						
Sprinklers:			S	Flue Supply:	🛛 I 🗌 NI	🗌 NP 🗌 D 🔲 S						
Other:		🛛 NP 🗌 D	S	Other:		🛛 NP 🗌 D 🔲 S						
ELECTRICAL:			Inspe	ected : 🔵 Yes	<mark>O</mark> No							
Main Panel:	🛛 I 🗌 NI	□NP □D	□s	Ground:	🛛 I 🗌 NI	□NP □D □S						
Service:	🛛 I 🗌 NI	□NP □D	⊡s s	moke / Carbon								
Branch Wiring:	🗆 I 🛛 NI	□NP □D	□s	Monoxide Detectors:								
G.F.C.I.:	🛛 I 🗌 NI	□NP □D	S	Other:	🗌 I 🔲 NI	🖾 NP 🗌 D 🔲 S						
HEATING / COOLING: In:			Inspe	ected : 🔵 Yes	O No							
Heating:		□NP □D	S	Ducting:	🛛 I 🗌 NI	□NP □D □S						
Venting:			□s	Cooling / AC:		🛛 NP 🗌 D 🔲 S						
Combustion Air:			□s	Other:		NP D S						
Thermostat:			□s									
	· · · · · · ·											

ſ

Report #: Dell061320	015	U	Unregistered Software Call: 760.450.2026 or 760.650.1255						
Client: Donald De						2003-115 El Camino Real			
Property: 1121 Any S		Ca 92038				Oceanside CA 92054			
Inspection Date: June	e 13, 2015			lde	entifyReport@	-			
					Your Ir	nspector's Name, Inspector			
I = Inspected NI = Not Inspected		NP = Not Present		= Defect	S = Safity Issue				
GARAGE			Inspected	d: 🔍 Yes	O No				
Slab / Floor:		NP 🛛 D	🗌 S 🛛 Ga	rage Roof:	🛛 I 🗌 NI	□NP □D □S			
Fire Door:		NP 🗌 D	🗌 S 🛛 Ga	rage Attic:					
Fire Wall:		NP 🗌 D	S Ce	iling:					
Access Door:		NP 🗌 D	🗌 S 🛛 Wa	alls:					
Vehicle Door:		NP D	🗌 S 🛛 Do	oors:	🛛 I 🗌 NI	□NP □D □S			
Automatic Opener:			S Wi	ndows:					
Electrical:			S Sc	reens:	🗌 I 🔲 NI	🛛 NP 🗌 D 🔲 S			
Vents:		NP D	S Otl	her:	🗌 I 🔲 NI	🛛 NP 🗌 D 🔲 S			
LAUNDRY: Inspected : O Yes No									
Counter Tops:		NP 🗌 D	□s _{Ce}	iling:	🛛 I 🗌 NI	□NP □D □S			
Cabinets:		🛾 NP 🔲 D	S	alls:					
Washer:		NP 🗌 D	S	Dors:					
Dryer & Vents:				oors:					
Electrical:			S Wi	ndows:					
Sinks: Drains:			S Sc	reens:					
Exhaust Fan:			S Otl	her:					
Exhaust Fan.		NP 🗌 D	∟s						
POOL / SPA None Inspected : O Yes No									
Deck Surface:		NP 🗌 D	□s Pu	mps:		NP D D S			
Pool / Spa Surface:				ower / Bubbler:					
Diving Board / Slide:			— • •	a Jets:					
Hand Rails:		_	-	ectrical:					
Fences / Gates:			<u> </u>	ner:					
Pool / Spa Heater:		_		emote:					
Pool / Spa Filters:				her:		$\square NP \square D \square S$			
THERMAL IMAGES Inspected : O Yes No									
Thermal Images		⊠ I □ NI) 🗌 S					

SUMMARY

Unregistered Software Call: 760.450.2026 or 760.650.1255

2003-115 El Camino Real

Report #:Dell06132015Client:Donald DellProperty:1121 Any Street La Jolla, Ca 92038Inspection Date:June 13, 2015

Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name, Inspector

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

All Major Defects Are In RED

Minor Defects are In Black Re Inspected On 06/21/2015 All Previous Defects Confirmed

FOUNDATION / STRUCTURE:

Property Owners Association / Park Management Statement

EXTERIOR:

Exterior Electrical:

Inoperable / Broken Light found at: Rear Patio Bedroom Next to sliding Doors See Photo # 13, 14

Exterior Enter Enter:

Moisture noted on Exterior brick Walk way, Recommend redirecting water for greenery.

See Photo # 19,20,21,22,23,24

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

Exterior Surface: Stucco surface is cracked / damaged at several areas. See Photo # 15, 16, 1, 18 See Photo # 15, 16, 1, 18 See Property Owners Association / Park Management Statement

ROOF / ATTIC: Garage Roof is a Flat Roof, seems to be New. See Property Owners Association / Park Management Statement

CHIMNEY / FIREPLACE: FIREPLACE See Photo # 37. Need to install a gap device Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

INTERIOR ROOMS:

Entry Hall: Closet has things stored, Doors needs adjusted will not stay Closed See Photo # 49 Entry Hall: Danger:Trip Hazard, Hall Entry To Down Stairs See Photo # 51 Entry Hall: Cracks Noted On Wall above Garage Entry Door. See Photo # 57 Entry Hall: Floor Damaged at Bottom of Garage Enter Door. See Photo # 59 Entry Hall: Entry Door Damaged, Molding Damage. See Photo # 60

Master Bedroom: Sliding door hard to open and close and will not Lock. Needs repair/ Replacement. See Photo # 56, 58 Master Bedroom: Sliding Glass Door Will Not Lock Hard to Open or Close See Photo # 55

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.

(6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

SUMMARY

Unregistered Software Call: 760.450.2026 or 760.650.1255

2003-115 El Camino Real

Report #:Dell06132015Client:Donald DellProperty:1121 Any Street La Jolla, Ca 92038Inspection Date:June 13, 2015

Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name, Inspector

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

Bedroom # 2 Bedroom 2: Wall above Sliding doors Needs Repair, See Photo # 52

Bedroom # 2 Slinging Door Hits Door When Closing See Photo # 55

Bedroom # 2 Heater Vent, Wall damage See Photo #53

Bedroom # 2 Moisture Noted at Sliding glass Door. See Photo # 54

Bedroom # 2 Moisture Noted at Wall. See Photo # 159

Living Room: Noted Added Electric Out Let. See Photos # 157, 158

Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a qualified licensed contractor / specialty trades person.

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

KITCHEN:

Disposer electric plug needs repair / Replace. **Kitchen in Wall Moisture Noted With Moister Probe in Several Areas.** See Photo # 62, 63, 64, 65 Cabinet Door Under Sink Damaged See Photo # 65 Damaged Garnet Counter Top at Left of Sink, Missing Quarter Round. See Photo # 68 Gap Noted at Kitchen sink, Needs Calking to prevent Water Damage. See Photo # 67 Floors: Tile is Not Sealed to Floor, May come Loose. See Photo # 66

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

BATHROOMS:

Upstairs Bathroom 1/2 Bath. Fan Needs Repaired/Replaced, Makes Lots of Nose. See Photo 76

Master Bathroom

Sinks: Sink drain Pop Up Stopper needs repair / adjustment at one or more locations. See Photo # 73 Master Bath Tub Danger: Bath Tub Light Not to Code. May Result in Electric Shock See Photo # 74 Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a qualified licensed contractor / specialty trades person.

All Bathroom Sinks, Tubs and Counters Need re-calking. See Photo # 75, 77 Upstairs Bathroom

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

PLUMBING:

Water Heater: May be at end of life, Makes popping sound when turned on to test. See Photo # 85 Water Heater: Hot Water Heater Shut off Valve Corroded . See Photo # 86

ELECTRICAL:

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

SUMMARY

Unregistered Software Call: 760.450.2026 or 760.650.1255

2003-115 El Camino Real

Report #:Dell06132015Client:Donald DellProperty:1121 Any Street La Jolla, Ca 92038Inspection Date:June 13, 2015

Oceanside CA 92054 IdentifyReport@gamil.com 760.650.1255

Your Inspector's Name, Inspector

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

Stab Lok Main & Sub panels and circuit breakers manufactured by Federal Pacific are suspected of having design flaws which can allow them to cause shock hazards and fires. We recommend replacement of these panels. Note also that electricians may not work on this equipment, and replacement parts may be difficult to find and expensive. See Photo # 97, 98

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

HEATING / COOLING:

Heating: Recommend cleaning/vacuuming furnace. See Photo # 109 Heating: Insufficient combustion air is provided to furnace / utility closet. Increase combustion air by adding vents, trimming bottom of door, or adding a louvered door.

Heating: Heater has a Flex Tub Installed ware a Steel Line Needs to Be to Prevent Gas Leek. See Photo # 110

Recommend evaluation or repairs by a Qualified licensed contractor / specialty trades person.

GARAGE Garage: Stain on Wall. See Photo # 121

COMMENTS AND NOTES:

Property Owners Association / Park Management Statement

The residential dwelling unit appears to be part of a complex that is maintained by a property owners association and / or park management. The inspection will be limited to a visual evaluation of the items, systems, components and associated features that are located within and adjacent to the dwelling unit inspected. The current condition of any "common elements" such as, but not limited to, stairs; landings; porches; hallways; balconies; decks; patios; pools; spas; recreational areas / equipment; elevators; utility metering; parking stalls / ports; building site condition; structural stability; and all common areas are not considered to be part of the inspection report. Any comments made regarding same, have been made as a courtesy only, and should be addressed to the property owners association / park management or their representative. It is suggested that the property owners association / park management operation budget, including a reserve study, be carefully reviewed. The reserve study should provide an awareness as to the anticipated remaining life expectancies of the major components and systems. The budget should also include a statement of the present funds, and a funding strategy to cover future major repair and / or replacement. Approved or anticipated special assessments should also be addressed. It is also suggested that the current property owner be consulted regarding known past defects, all corrective work performed, and to thoroughly review the "C. C. & RS" and reserve study for disclosure of any pertinent facts affecting the current condition and market value of the property, the properties common elements and areas, and any existing or pending litigation.

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.

(6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.