



Unregistered Software 1-760-650-1255

Your Company Address
Tampa Florida 32569
850-737-1234 inspector@gmail.com



Report # / I.D : Samp070612

Inspection Date : July 12 2012

Time : 9am

Client Name : Mr Sample Client

Property Address : 411 Circle Caviar, Murrieta, Ca, 92562

Buyers Agent :

Donald Smith

Donald Smith

Company : Re-Max Associates

Re-Max Associates

Address : 707 Escondido Ave

707 Escondido Ave

City, St, Zip : Thousand Oaks CA.

Thousand Oaks CA.

Office / Fax : 860-643-3700

860-643-3700

This report is the privet property of Mr Sample Client Do Not Copy or Reproduce.

INSPECTION CONDITIONS / GENERAL PROPERTY INFORMATION

Type Of Inspection: Pre-Purchase Inspection

Home Type / Style: Single Family Home

Number Of Units: 1

Age / Year built: 1990

Square Footage: 3000

Conditioned: Yes

Inspection Time Start: 9am

End: 3:00

Inspection Attendees: Buyers & Sellers Agent

Furnishings: Part furnished

Main Electrical Disconnect Location:

Main Water Shut Off Location: Located At:

Main Gas Shut Off Location: Located At:

Weather Conditions: @ start Clear

Temperature: 80

Soil Condition: Soil Condition: Good

Other Conditions of Note:
(Occupants were in the process of packing)

Index

Ppage 1	Cover Page
Selection 2	Legend / Property Description
Selection 3	Foundation
Selection 4	Exterior
Selection 5	Roof
Selection 6	Chimney F/p
Selection 7	Interior
Selection 8	Kitchen
Selection 9	Bathroom
Selection 10	Plumbing
Selection 11	Electrical
Selection 12	Heating
Selection 13	Garage
Selection 14	Laundry
Selection 15	Pool/Spa
Selection 16	Comments
Selection 17	Other
Selection 18	Summary

THE INSPECTION REPORT LEGEND & INTRODUCTION PAGE

THE BRACKETED NUMBERS ARE DEFINED AS FOLLOWS:

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of infestation / deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

Note: Most of the time the deficiency will just be noted. If it is a Possible Safety Hazard it will be noted. I always recommend a licensed professional in the related field do examinations & or repairs.

Anytime these statements: Appears to be mold or mildew type substance, mold/mildew is visible are used, mold may be a health & or safety issue & need further inspection & or remediation by a specialist.

The term " Satisfactory/Functional " or " Appears Satisfactory/Functional " Is used to identify an item or component that was

found to be functionally usable at the time of the Property Inspection. Normal wear & tear is not noted.

THE PURPOSE OF THE PROPERTY INSPECTION

The Property Inspection is a Non-Invasive physical examination designed to identify material defects in the systems / structures / components of the building as they exist at the time of The Property Inspection.

The Property Inspection is limited to those systems / structures / components that are present & accessible.

Components / Systems shall be operated with normal user controls only & as conditions permit.

The Inspection Report may contain recommendations for evaluations / testing / repairs / upgrades / inquiries or comments about an item or condition that should be brought to the Client(s) attention.

THE PROPERTY INSPECTION OUTLINE

The Client(s) are invited & encouraged to accompany the Property Inspector during The Property Inspection process.

When completed, The Property Inspection will be reviewed on site, assuming the Client(s) are present.

The Report identifies separate areas, such as Electrical / Plumbing / Heating / Roof / Bathrooms, etc.

If The Client(s) have any Questions / Comments, Please Call The Inspector As Soon As Possible.

The Inspector works solely for the Client(s), not the Agents or Sellers.

The Inspector has no vested interest in whether or not The Property purchase is completed.

The Inspector does not perform repairs / referrals for repairs, to Prevent a Conflict of Interest.

The Inspection Report is not a Warranty or Guarantee of any kind. If a Home Warranty is not provided by the Sellers, Agents or Others. The Client(s) are is strongly advised to obtain one.

The use of the Inspection Report is authorized for the sole use of The Client(s) identified on The Contract.

The Inspector / Inspection Company has no contractual obligations or fiduciary responsibility to any third parties / agents / future purchasers or any other persons that may come into possession of The Inspection Report.

By initialing below the Client(s) or Client(s) Real Estate Agent / Representative, acknowledges reading & understanding the Inspection Report Legend / The Purpose of the Inspection / The Inspection Outline / The Report Summary and The Inspection Report Contract, including The Standards of Practice.

Client Initials. _____ Date. _____ Client Initials. _____ Date. _____

Initials of Client(s) Real Estate Agent / Representative only if client(s) are not able to attend the inspection.

Initials of Client(s) Real Estate Agent / Representative. _____ Date. _____

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client
Inspection Date: July 12, 2012

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Unregistered Software 1-760-650-1255

Your Company Address
Tampa Florida 32569
850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

FOUNDATION

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the foundation / structure were observed to determine their condition at the time of inspection. The condition of foundations / slabs / subfloors not visible due to carpet / floor coverings cannot be determined. The wall surfaces or design configuration of the structure often prevents access to visually verify the presence or condition of anchor bolts. If any foundation damage / deterioration / infestation is reported the client is strongly advised to obtain the services of a qualified licensed structural engineer / Geotechnical engineer / termite / pest inspector & consider any recommendations for repair / replacement / treatment prior to the close of escrow. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

FOUNDATION TYPE	Type Is: Poured Concrete
UNDER FLOOR ACCESS	N/a-
UNDER FLOOR VENTILATION	N/a
STRUCTURE TYPE	Single Family Home & Cross Braced / Blocked
FLOOR FRAMING	Not Visible- Concrete
VAPOR RETARDER	Not Visible
INSULATION	Located At: Type Is:
BEAMS & PIERS	Type Is: Type Is:

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



Slab was not visible due to carpet / floor coverings. Does not appear to be cause for concern at the time of inspection.

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

EXTERIOR:

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the exterior surfaces / trim were observed to determine their condition at the time of inspection. Destructive testing of exterior wood surfaces / trim to determine the presence of any deterioration / infestation is beyond the scope of this report. Damaged / infested areas reported should be repaired / treated by appropriate specialist. The routine maintenance of door & window frames is required to prevent damage / leaks. The client is strongly advised to obtain & review the termite / pest report & consider any recommendations for repair / treatment of the property prior to the close of escrow. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

EXTERIOR SURFACES Type:

TRIM Type:

SURFACE GRADE Acceptable- See Comments

DRIVEWAYS / SIDEWALKS Concrete Stairs Are: Concrete

EXTERIOR DOORS Wood & Sliding Glass Doors Hose Bibs Are: functional

WINDOWS MAT./PLANT LIFE Vinyl- Dual Pane Glass Needs Trimming-see Comments

PATIOS / PORCHES Concrete Porch(s)- Retaining Wall Is Block

FENCES & GATES Chain Link- Retaining Wall Drainage Is Not Visible

SOIL CONDITION: Soil Condition: Good

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



Recommended evaluation by a licensed structural engineer / Geotechnical engineer.

Surface Grade: Lot drainage is flat or slopes toward the house at rear.

Surface Grade: Recommend installing window wells & or covers at basement windows.

Exterior Fences and Gates



Loose / leaning / gaps & there is potential for small pets to escape.

SIDEWALKS

Sidewalks: Small / moderate cracks noted. No adjacent damage found.

Unable to fully evaluate exterior, grounds, and drainage components due to the presence of frozen ground, snow, & ice.

Exterior Staircase: No hand / guard railing provided at: *** (2) (5)



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

EXTERIOR:

FRONT OF HOUSE Facing Direction:



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

ROOF / ATTIC:

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the roof / roof penetrations / flashings & attic space were observed to determine their condition at the time of inspection. Roofs will only be inspected by walking on their surfaces if reasonably accessible / if doing so will not cause any damage to the roof / endanger the inspector. Reporting if a roof has an active leak is not possible unless the leak is observed at the time of inspection. Reporting remaining life expectancy / predicting future roof leaks is beyond the scope of this report. If damaged / deteriorated / missing areas are reported the client is advised to obtain the services of a qualified licensed roofing contractor for further evaluation prior to the close of escrow. The testing of gutters / down spouts / underground drains is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

ROOF MATERIAL/VALLYS

Tile & Roll Comp

ROOF SHEATHING

Material Is: Plywood

ATTIC / ROOF FRAMING

Pre-fab Truss System Vapor Barrier

ATTIC ACCESS & LOCATION

Limited-see Comments Below Located At:

ATTIC INSULATION

Acceptable- Type Is:

ATTIC VENTILATION

Gable & Soffit

FLASHINGS

Appear Acceptable

GUTTERS / DOWNSPOUTS

Refer To Comments Below- Refer To Comments Below

SKYLIGHTS/KITCHEN & BATH

Appear Acceptable- Bathroom Roof Vents (If Present)

Shingles

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.




Shingles need secured & sealed at one or more locations.



View of trim that needs secured




View of roof



View of elect over garage



Shingles showing signs of weathering & age.



Wire in over hang



Main Roof: Recommend removal of vegetation from eaves / roof surfaces / edges. (2)

Main Roof: Cracked / broken / displaced shingle found. (2)

Roof viewed from ground at time of inspection due to pitch/steepness of roof. Does not permit safe & easy access. Roof does show some signs of weathering & age. If you want a full roof inspection & an estimate of life left in shingles consult one or more licensed roofing contractors.

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

ROOF / ATTIC:

FRONT OF HOUSE Facing Direction:

Main Roof: Active roof leak found at: *** (2)

Roof appears to be part of a multi family unit & appears to be the responsibility of the association. Inspection Limited.

Main Roof Comment: Recommend roofing evaluation / repair due to several areas of cracked / loose / deteriorated / missing mastic / sealant around vents / joints / edges. (2)



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Unregistered Software 1-760-650-1255

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

CHIMNEY / FIREPLACE:

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the fireplace / chimney were observed to determine their condition at the time of inspection. Associated mechanical features are tested by operating their normal controls to verify proper function. Reporting on chimney draw / performing a smoke test / ignition of wood / gas / the use of video equipment is beyond the scope of this report. If damaged / deteriorated / inoperable / unsafe items / features are reported the client is advised to obtain the services of a qualified licensed chimney contractor / specialist for further evaluation / testing prior to the close of escrow. Gas logs controlled by a switch / thermostat found shut off / that have shut off pilots will not be tested & pilots will not be lighted. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

Caps at roof:

Present- Bird Guard Is:

SPARK SCREEN AT FIREPLACE

Is: Spark Arrester @ Roof:

SPARK SCREEN AT STOVE

Is Present

DIRECT VENT GAS FIREPLACE

Is:

WOOD BURNING FIREPLACE

Is: Hearth is Acceptable

LIVING ROOM CHIMNEY

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



Chimney: Recommend evaluation by a qualified specialist to determine if the spark arrester / shroud are approved / listed for use with this fireplace & chimney. (2)

Chimney / Fireplace: Keep in mind that the fireplace is a direct vent unit & the chimney is at the porch/patio area/deck. This poses a possible safety concern since it gets very hot when fireplace is in use. Be sure not to touch or keep items stored close to the chimney.

Chimney: Flat screen across chimney top could be blocked by floating embers and is not provided with a rain cap. (2) (5)

Chimney: Flashing requires repair / resealing where chimney penetrates the roof surface. (2)

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Unregistered Software 1-760-650-1255

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

INTERIOR ROOMS:

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the interior rooms were observed to determine their condition at the time of inspection. A comparative sample of the windows / doors / closets / cabinets / outlets / switches / fixtures were observed / tested to determine their condition at the time of inspection. Furniture / clothing will not be moved to test outlets / inspect walls / floors. Dual Pane seal failure will be reported where observed, however, weather / temperature / light changes can make identifying all problems difficult / impossible. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

WALLS / CEILINGS

Drywall / Plaster Walls

FLOORS

Type:

DOORS

Wood

WINDOWS & SCREENS

Material Is: Type Is:

STAIRS / RAILINGS

Is:

ELECTRICAL

See Electrical Section & Ceiling Fans

CABINETS / CLOSETS

Are:




Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



Floors: There are some signs of water damage to laminate flooring. This is common when water gets into seams of this flooring. Recommend gluing seams where there is more of a chance of moisture penetrations, such as at entryways, near sinks, tubs, toilets. This will help reduce damage over time.

Recommend adding additional bracing to garage rafters since it appears that one has been cut into when door opener was installed some time ago. This is a possible structural concern.

Ceilings: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

INTERIOR ROOMS:

FRONT OF HOUSE Facing Direction:



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

KITCHEN:

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the kitchen were observed to determine their condition at the time of inspection. Associated built in appliances / fixtures / counters / cabinets / sinks / drains were observed / tested to determine their condition at the time of inspection. Appliances are not checked for temperature calibration / timer function / microwave oven radiation leaks. Testing water filter / purification equipment / instant hot water heating equipment is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

Counters / Cabinets / Drawers

Sinks / Faucets

Garbage Disposal

Built In Dishwasher

Fridge

Ice Maker

Built in microwave

vent hood

RANGE TYPE:

OVEN TYPE:

WetBar Sink Plumbing(If PRESENT)

GFCI (IF PRESENT)

Exhaust / Vent Hood

Exhaust / Vent Hood

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.




Cosmetic damage at kitchen sink.

Sinks: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Faucets: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Faucets: Leaks when operated. (2)

Cabinets: Sprung / broken hinges found at one or more cabinet doors. (2)



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

KITCHEN:

FRONT OF HOUSE Facing Direction:



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

BATHROOMS:

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the bathrooms were observed to determine their condition at the time of inspection. Associated built in appliances / fixtures / counters / cabinets / sinks / drains were observed / tested to determine their condition at the time of inspection. Verifying the presents / temperature setting of no shock faucets / fixtures / determining if shower pans, tub / shower enclosures are water tight is beyond the scope of this report. Capacity of the water heater to serve the demands of a spa tubs is not reported. Any comments about the bathroom floors, walls, ceilings, doors, windows are located at the interior rooms page. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

Locations: Hall & Master Bathroom

Sinks & Sink Fixtures

Bathtubs & Tub Fixtures

Showers & Shower Fixtures

Toilets

Exhaust Fan

Whirlpool Tub

Counter / Cabinets / Drawers

Traps / Drains / Supply

GFCI outlets(If Present)

Bathroom Titles 7 Bathroom SubTitles 7 Bathroom SubSubTitles 7

Bathroom Titles 8

Bathroom Titles 9

Bathroom Titles 10

Bathroom Titles 11

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.




View of bathroom vent fan venting into attic space



Sinks: No Functional / Mechanical Defects Found To Report At The Time Of Inspection. Sinks: Porcelain surface is chipped at: *** (2)

Sinks: Porcelain surface is chipped at: *** (2)



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

BATHROOMS:

FRONT OF HOUSE Facing Direction:



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

PLUMBING:

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the main water line, shutoff valve, water supply lines, drain / waste pipes & gas meter / pipes were observed to determine their condition at the time of inspection. Leaks, damage, corrosion of the plumbing system concealed from view / located underground cannot be reported by a visual inspection. Fixture shutoffs including those serving kitchen, bathrooms, wet bar sinks, laundry, etc. are not tested due to risk of causing a leak requiring immediate repair. Testing of water softeners, water filters, sump pumps as well as the testing of solar systems serving water heaters / pools / spas are beyond the scope of this report. Gas meters found shut off will not be turned on & gas appliances found shut off will not be tested & pilots will not be lighted. Some A B S plastic drain / waste pipe systems have experienced problems. Identifying when or by what company these materials were manufactured is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

WATER METER

Located At:

WATER SHUT OFF VALVE

Located At:

WATER SUPPLY LINE

Material Is: Water Pressure

WATER HEATER BRAND

Brand Is: Type Is:

FUNCTIONAL WASTE DRAIN

Material Is: Water Heater Is Approx:

GAS METER/SHUT OFF LOC.

Located At: Water Heater Is Located At:

WATER HEATER TPR PIPE

Is

WATER & SEWER:

Are:

GAS PIPING

Type Is:

WATER HEATER INFO:

Model # Serial #

PLUMBING TITLES 11

PLUMBING TITLES 12

PLUMBING TITLES 13

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



No Functional / Mechanical Defects Found To Report At The Time Of Inspection.No Functional / Mechanical Defects Found

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

PLUMBING:

FRONT OF HOUSE Facing Direction:

To Report At The Time Of Inspection.

Water Meter: Unable to locate the water meter. Recommend contacting the seller / water company or the property owners association to determine the location of the meter. (2)

Water Meter: Unable to locate the water meter. Recommend contacting the seller / water company or the property owners association to determine the location of the meter. (2)



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

ELECTRICAL:

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the service entrance, grounding system, main / sub panels were observed to determine their condition at the time of inspection. Lights & accessible outlets / switches are checked for basic operation. Smoke detectors will be tested only if accessible & provided with a built in activation button / switch. The function of time clocks is not verified. The location & operation of ground fault circuit protection (G. F. C. I.) will be identified. Light fixtures that have missing or broken bulbs are considered nonfunctioning. Motion sensor / dusk to dawn light fixtures & low voltage yard lights are not tested. Electrical equipment found disconnected / dismantled will not be tested. Determining the adequacy / efficiency of the overall electrical system is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

SERVICE ENTRANCE

Type:

MAIN PANEL LOCATION/ BRAND

Located At: Brand Is:

MAIN BREAKER/ CIRCUIT TYPE

Located At: Type Of Circuits Are:

PANEL RATING AMP/VOLTAGE

Located At

BRANCH CIRCUIT WIRING

Material Type: Wire Type:

GROUND FAULT DEVICES

At:

SMOKE DETECTORS

See Comments

ALUMINUM WIRING VISIBLE

Is:

MAIN PANEL SERVICE WIRE

Type Is:

MAIN SERVICE GROUND




Type Is:

MAIN ELECTRICAL DISCONNECT

ELECTRICAL TITLES 12

ELECTRICAL TITLES 13

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



Main Panel: The connection of two or more conductors to a single breaker, called Double Tapping, was found in the Main Panel. This condition can cause overheating / breaker malfunction / fire. Possible Safety Hazard

Main Panel: Circuit Breaker labels are missing / incomplete / Illegible.

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

ELECTRICAL:

FRONT OF HOUSE Facing Direction:

Missing knock out plug(s) at main panel. Possible Safety Hazard

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

HEATING / COOLING

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the heating / cooling units, associated electrical / gas connections, vents, ducting & filters were observed to determine their condition at the time of inspection. Heating / cooling systems are tested by operating normal controls / thermostats to verify proper function. Checking for cracks / damage to heat exchangers & dismantling the components of heating / cooling systems is beyond the scope of this report. Heating / cooling systems found shut off / that have shut off pilots will not be tested & pilots will not be lighted. Heating / cooling systems are not evaluated for efficiency or adequacy. Thermostats are not checked for calibration / timer functions. Some makes / models of horizontal gas heaters are involved in a safety recall, this determination requires the services of a qualified licensed heating contractor / specialist. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

PRIMARY HEATING SYSTEM THERMOSTATS / CONTROLS DUCTING

Type: Located At The Hall

Located At

Type: Distribution

VENTING / COMBUSTION AIR AIR FILTERS

Type: Ac Temperature Diff: See Comments

See Comments Below- Furnace Age Is Approx.

CENTRAL AIR CONDITIONING

Located At Exterior- Ac Age Is Approx.

HEATING BRAND IS:

Model # Serial #

AC BRAND IS:

Model # Serial #

Heating A/C Title 9

Heating Sub Title 9 Heating 9 Sub Title 2

Heating A/C Title 10

Heating Sub Title 10 Heating 10 Sub Title 2

Heating A/C Title 11

Heating A/C Title 12

Heating A/C Title 13

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



Heating / Cooling Comment: Recommend having heat and A/C serviced annually.

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client
Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

HEATING / COOLING

Heating: Small gas leak detected at furnace at main control valve. See Photo

Unregistered Software 1-760-650-1255

Your Company Address
Tampa Florida 32569
850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

FRONT OF HOUSE Facing Direction:



REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

GARAGE

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the garage / carport were observed to determine their condition at the time of inspection. Associated mechanical equipment is tested by operating normal controls to verify proper function. Fire door self closing devices / automatic garage door openers / garage electrical / access doors / windows are checked for proper / safe function. Comments about equipment / appliances located inside the garage / carport i. e. electrical panels / laundry / water heaters / water softeners / heating / cooling equipment / water shut off / yard sprinkler controls / timers etc. will be found on their appropriate pages of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

SLAB / FLOOR

Material Is:

FIRE WALL / DOOR

Is:

WALLS & CEILINGS

Are:

ACCESS / SIDE DOOR

Is:

VEHICLE DOOR / OPENER

Is:

REMOTE OPENERS

Is:

TYPE OF GARAGE

Is:

GARAGE ELECTRICAL

Is: Garage Heater (IF PRESENT)







GARAGE TITLES 9

GARAGE TITLES 10

GARAGE TITLES 11

GARAGE TITLES 12

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



Slab / Floor: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Slab / Floor: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Slab / Floor: Typical Cracks

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

LAUNDRY:

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the laundry room / area were observed to determine their condition at the time of inspection. The washer hook ups / drain connections / fixtures / counters / cabinets / sinks / drains / outlets / switches were observed / tested to determine their condition at the time of inspection. Testing the washer / dryer by running the equipment through a wash / dry cycle is beyond the scope of this report. However, washer will be tested to ensure it fills & drain water, & dryer will be tested to ensure it heats up. Washing & Drying capabilities will not be tested. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

Counters / Cabinets / Shelves

Washer Hook Ups

Traps / Drains / Supply

Washer

Laundry Tiles 7

Laundry Tiles 8

Laundry Tiles 9

Laundry Tiles 10

Laundry Sink & Faucet

Dryer Vent

Grounded Outlet Provided

Washer Hook Ups

Current Dryer Is :

Laundry Sink & Faucet

Vent Fan

Dryer Hook Up Is Gas

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Counter Tops

Counter Tops

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

POOL / SPA None

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

Pool / Spa Part: 1

FRONT OF HOUSE Facing Direction:

NOTICE: The visible portions of the pool / spa were observed to determine their condition at the time of inspection. Associated equipment / light fixtures / outlets / switches / timers / valves / heaters / pumps / equipment ground bonding / ground fault protection (G. F. C. I.) were observed / tested to determine their condition at the time of inspection. Equipment found shut down / empty / dismantled / will not be tested. Testing / evaluation of function / efficiency solar systems & their associated features is beyond the scope of this report. Determining the presents of underground leaks / damage is beyond the scope of this report. Associated items / components that are concealed from view / inaccessible at the time of inspection are excluded from this report.

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

THIS PROPERTY HAS AN IN GROUND POOL & SPA

POOL STYLE / MATERIAL

SPA STYLE / MATERIAL

HEATER

FILTER

PUMPS

BLOWERS

ELECTRICAL

FENCES / GATES

FEATURES

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



none

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

Unregistered Software 1-760-650-1255

Report Prepared For: Mr Sample Client

Property Inspected: 411 Circle Caviar, Murrieta, Ca, 92562

Report #: Samp070612

INSPECTION REPORT

Inspector : Inspectors Name

07/12/12, 9:00 AM

OTHER SYSTEMS:

FRONT OF HOUSE Facing Direction:

The Following Items / Components & Associated Features Present At The Time Of Inspection Were Found To Be In Satisfactory Condition Unless Noted Below.

SMOKE DETECTORS

Located At The

YARD SPRINKLER SYSTEM

Served By

CENTRAL VACUUM SYSTEM

Located At The

FIRE SPRINKLER SYSTEM

Refer To Comments Below

ELEVATOR

SPECIAL FEATURE

Other Titles 7

Other Titles 8

Other Titles 9

Other Titles 10

Recommendations For Evaluations / Repairs / Upgrades / Inquiries & Comments Noted Below.



Comment Title 2

Add Comments

Add any Appliance Comments: 00

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

INSPECTION REPORT

Report #: Samp070612

Client: Mr Sample Client

Property: 411 Circle Caviar, Murrieta, Ca, 92562

Inspection Date: July 12, 2012

Unregistered Software 1-760-650-1255

Your Company Address

Tampa Florida 32569

850-737-1234 inspector@gmail.com

Inspector: Inspectors Name

COMMENTS AND NOTES:

FRONT OF HOUSE Facing Direction:



Comments

Security Alarm System: Testing / evaluation of this system is beyond the scope of this report. (2) additions / alterations noted but not necessarily limited to the Following items / components / associated features listed below. unable to determine if any of this work was done with required permits or by qualified licensed contractors / specialty trades persons. client is strongly advised to obtain & review as complete a permit history on this property as is available prior to close of escrow.

Property Owners Association / Park Management Statement

The residential dwelling unit appears to be part of a complex that is maintained by a property owners association and / or park management. The inspection will be limited to a visual evaluation of the items, systems, components and associated features that are located within and adjacent to the dwelling unit inspected. The current condition of any "common elements" such as, but not limited to, stairs; landings; porches; hallways; balconies; decks; patios; pools; spas; recreational areas / equipment; elevators; utility metering; parking stalls / ports; building site condition; structural stability; and all common areas are not considered to be part of the inspection report. Any comments made regarding same, have been made as a courtesy only, and should be addressed to the property owners association / park management or their representative. It is suggested that the property owners association / park management operation budget, including a reserve study, be carefully reviewed. The reserve study should provide an awareness as to the anticipated remaining life expectancies of the major components and systems. The budget should also include a statement of the present funds, and a funding strategy to cover future major repair and / or replacement. Approved or anticipated special assessments should also be addressed. It is also suggested that the current property owner be consulted regarding known past defects, all corrective work performed, and to thoroughly review the "C. C. & RS" and reserve study for disclosure of any pertinent facts affecting the current condition and market value of the property, the properties common elements and areas, and any existing or pending litigation.

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

COMMENTS AND NOTES**Unregistered Software 1-760-650-1255****Report #: Samp070612**

Your Company Address

Client: Mr Sample Client

Tampa Florida 32569

Property: 411 Circle Caviar, Murrieta, Ca, 92562

850-737-1234 inspector@gmail.com

Inspection Date: July 12, 2012

Inspector: Inspectors Name

Part : 1

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

FOUNDATION

Slab was not visible due to carpet / floor coverings. Does not appear to be cause for concern at the time of inspection.

Address light not working (2) Photo #1

Rear Gate and Fence Damaged and leaning, at end of life, Noted Earth to wood contact. See Photo # 2

FOUNDATION: Has typical cracks. This part of the inspection do to floor coverings, wall covering, ect. that obstruct the visibility of the structure itself. Appears to be ok at time of inspection.

Re tuck pointing needed at foundation of home.

Structure: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Re surfacing, tuck pointing, coating, painting needed at interior of foundation.(2)

Moisture / mildew stains on subfloor indicates that the area has experienced high humidity and poor ventilation during seasonal variations. Additional ventilation is recommended. Install additional ventilation.(2)

EXTERIOR:

Recommended evaluation by a licensed structural engineer / Geotechnical engineer.

Surface Grade: Lot drainage is flat or slopes toward the house at rear.

Surface Grade: Recommend installing window wells & or covers at basement windows.

Exterior Fences and Gates

Loose / leaning / gaps & there is potential for small pets to escape.

SIDEWALKS

Sidewalks: Small / moderate cracks noted. No adjacent damage found.

Unable to fully evaluate exterior, grounds, and drainage components due to the presence of frozen ground, snow, & ice.

Exterior Staircase: No hand / guard railing provided at: *** (2) (5)

ROOF / ATTIC:

Main Roof: Recommend removal of vegetation from eaves / roof surfaces / edges. (2)

Main Roof: Cracked / broken / displaced shingle found. (2)

Roof viewed from ground at time of inspection due to pitch/steepness of roof. Does not permit safe & easy access. Roof does show some signs of weathering & age. If you want a full roof inspection & an estimate of life left in shingles consult one or more licensed roofing contractors.

Main Roof: Active roof leak found at: *** (2)

Roof appears to be part of a multi family unit & appears to be the responsibility of the association. Inspection Limited.

Main Roof Comment: Recommend roofing evaluation / repair due to several areas of cracked / loose / deteriorated / missing mastic / sealant around vents / joints / edges. (2)

CHIMNEY / FIREPLACE:

Chimney: Recommend evaluation by a qualified specialist to determine if the spark arrestor / shroud are approved / listed

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

This report is the privet property of Mr Sample Client (Do Not Copy or Reproduce.

COMMENTS AND NOTES**Unregistered Software 1-760-650-1255****Report #: Samp070612**

Your Company Address

Client: Mr Sample Client

Tampa Florida 32569

Property: 411 Circle Caviar, Murrieta, Ca, 92562

850-737-1234 inspector@gmail.com

Inspection Date: July 12, 2012

Inspector: Inspectors Name

Part : 2

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

for use with this fireplace & chimney. (2)

Chimney / Fireplace: Keep in mind that the fireplace is a direct vent unit & the chimney is at the porch/patio area/deck. This poses a possible safety concern since it gets very hot when fireplace is in use. Be sure not to touch or keep items stored close to the chimney.

Chimney: Flat screen across chimney top could be blocked by floating embers and is not provided with a rain cap. (2) (5)

Chimney: Flashing requires repair / resealing where chimney penetrates the roof surface. (2)

INTERIOR ROOMS:

Floors: There are some signs of water damage to laminate flooring. This is common when water gets into seams of this flooring. Recommend gluing seams where there is more of a chance of moisture penetrations, such as at entryways, near sinks, tubs, toilets. This will help reduce damage over time.

Recommend adding additional bracing to garage rafters since it appears that one has been cut into when door opener was installed some time ago. This is a possible structural concern.

Ceilings: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

CEILINGS

Ceilings: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

KITCHEN:

Cosmetic damage at kitchen sink.

Sinks: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Faucets: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Faucets: Leaks when operated. (2)

Cabinets: Sprung / broken hinges found at one or more cabinet doors. (2)

BATHROOMS:

Sinks: No Functional / Mechanical Defects Found To Report At The Time Of Inspection. Sinks: Porcelain surface is chipped at: *** (2)

Sinks: Porcelain surface is chipped at: *** (2)

PLUMBING:

No Functional / Mechanical Defects Found To Report At The Time Of Inspection. No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Water Meter: Unable to locate the water meter. Recommend contacting the seller / water company or the property owners association to determine the location of the meter. (2)

Water Meter: Unable to locate the water meter. Recommend contacting the seller / water company or the property owners association to determine the location of the meter. (2)

ELECTRICAL:

Main Panel: The connection of two or more conductors to a single breaker, called Double Tapping, was found in the Main Panel. This condition can cause overheating / breaker malfunction / fire. Possible Safety Hazard

Main Panel: Circuit Breaker labels are missing / incomplete / Illegible.

Missing knock out plug('s) at main panel. Possible Safety Hazard

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

This report is the private property of Mr Sample Client (Do Not Copy or Reproduce.)

COMMENTS AND NOTES**Unregistered Software 1-760-650-1255****Report #: Samp070612**

Your Company Address

Client: Mr Sample Client

Tampa Florida 32569

Property: 411 Circle Caviar, Murrieta, Ca, 92562

850-737-1234 inspector@gmail.com

Inspection Date: July 12, 2012

Inspector: Inspectors Name

Part : 3

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

HEATING / COOLING

Heating / Cooling Comment: Recommend having heat and A/C serviced annually.

Heating: Small gas leak detected at furnace at main control valve. See Photo

GARAGE

Slab / Floor: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Slab / Floor: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Slab / Floor: Typical Cracks

LAUNDRY:

No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Counter Tops

Counter Tops

COMMENTS AND NOTES:**Comments**

Security Alarm System: Testing / evaluation of this system is beyond the scope of this report. (2) additions / alterations noted but not necessarily limited to the Following items / components / associated features listed below. unable to determine if any of this work was done with required permits or by qualified licensed contractors / specialty trades persons. client is strongly advised to obtain & review as complete a permit history on this property as is available prior to close of escrow.

Property Owners Association / Park Management Statement

The residential dwelling unit appears to be part of a complex that is maintained by a property owners association and / or park management. The inspection will be limited to a visual evaluation of the items, systems, components and associated features that are located within and adjacent to the dwelling unit inspected. The current condition of any "common elements" such as, but not limited to, stairs; landings; porches; hallways; balconies; decks; patios; pools; spas; recreational areas / equipment; elevators; utility metering; parking stalls / ports; building site condition; structural stability; and all common areas are not considered to be part of the inspection report. Any comments made regarding same, have been made as a courtesy only, and should be addressed to the property owners association / park management or their representative. It is suggested that the property owners association / park management operation budget, including a reserve study, be carefully reviewed. The reserve study should provide an awareness as to the anticipated remaining life expectancies of the major components and systems. The budget should also include a statement of the present funds, and a funding strategy to cover future major repair and / or replacement. Approved or anticipated special assessments should also be addressed. It is also suggested that the current property owner be consulted regarding known past defects, all corrective work performed, and to thoroughly review the "C. C. & RS" and reserve study for disclosure of any pertinent

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

This report is the privet property of Mr Sample Client (Do Not Copy or Reproduce.

COMMENTS AND NOTES**Unregistered Software 1-760-650-1255****Report #: Samp070612**

Your Company Address

Client: Mr Sample Client

Tampa Florida 32569

Property: 411 Circle Caviar, Murrieta, Ca, 92562

850-737-1234 inspector@gmail.com

Inspection Date: July 12, 2012

Inspector: Inspectors Name

Part : 4

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

facts affecting the current condition and market value of the property, the properties common elements and areas, and any existing or pending litigation.

OTHER SYSTEMS:

Add any Appliance Comments: 00

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

This report is the privet property of Mr Sample Client (Do Not Copy or Reproduce.

COMMENTS AND NOTES**Unregistered Software 1-760-650-1255****Report #: Samp070612**

Your Company Address

Client: Mr Sample Client

Tampa Florida 32569

Property: 411 Circle Caviar, Murrieta, Ca, 92562

850-737-1234 inspector@gmail.com

Inspection Date: July 12, 2012

Inspector: Inspectors Name

Part : 1

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

FOUNDATION

Slab was not visible due to carpet / floor coverings. Does not appear to be cause for concern at the time of inspection.

Address light not working (2) Photo #1

Rear Gate and Fence Damaged and leaning, at end of life, Noted Earth to wood contact. See Photo # 2

FOUNDATION: Has typical cracks. This part of the inspection do to floor coverings, wall covering, ect. that obstruct the visibility of the structure itself. Appears to be ok at time of inspection.

Re tuck pointing needed at foundation of home.

Structure: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Re surfacing, tuck pointing, coating, painting needed at interior of foundation.(2)

Moisture / mildew stains on subfloor indicates that the area has experienced high humidity and poor ventilation during seasonal variations. Additional ventilation is recommended. Install additional ventilation.(2)

EXTERIOR:

Recommended evaluation by a licensed structural engineer / Geotechnical engineer.

Surface Grade: Lot drainage is flat or slopes toward the house at rear.

Surface Grade: Recommend installing window wells & or covers at basement windows.

Exterior Fences and Gates

Loose / leaning / gaps & there is potential for small pets to escape.

SIDEWALKS

Sidewalks: Small / moderate cracks noted. No adjacent damage found.

Unable to fully evaluate exterior, grounds, and drainage components due to the presence of frozen ground, snow, & ice.

Exterior Staircase: No hand / guard railing provided at: *** (2) (5)

ROOF / ATTIC:

Main Roof: Recommend removal of vegetation from eaves / roof surfaces / edges. (2)

Main Roof: Cracked / broken / displaced shingle found. (2)

Roof viewed from ground at time of inspection due to pitch/steepness of roof. Does not permit safe & easy access. Roof does show some signs of weathering & age. If you want a full roof inspection & an estimate of life left in shingles consult one or more licensed roofing contractors.

Main Roof: Active roof leak found at: *** (2)

Roof appears to be part of a multi family unit & appears to be the responsibility of the association. Inspection Limited.

Main Roof Comment: Recommend roofing evaluation / repair due to several areas of cracked / loose / deteriorated / missing mastic / sealant around vents / joints / edges. (2)

CHIMNEY / FIREPLACE:

Chimney: Recommend evaluation by a qualified specialist to determine if the spark arrestor / shroud are approved / listed

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

This report is the privet property of Mr Sample Client (Do Not Copy or Reproduce.

COMMENTS AND NOTES**Unregistered Software 1-760-650-1255****Report #: Samp070612**

Your Company Address

Client: Mr Sample Client

Tampa Florida 32569

Property: 411 Circle Caviar, Murrieta, Ca, 92562

850-737-1234 inspector@gmail.com

Inspection Date: July 12, 2012

Inspector: Inspectors Name

Part : 2

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

for use with this fireplace & chimney. (2)

Chimney / Fireplace: Keep in mind that the fireplace is a direct vent unit & the chimney is at the porch/patio area/deck. This poses a possible safety concern since it gets very hot when fireplace is in use. Be sure not to touch or keep items stored close to the chimney.

Chimney: Flat screen across chimney top could be blocked by floating embers and is not provided with a rain cap. (2) (5)

Chimney: Flashing requires repair / resealing where chimney penetrates the roof surface. (2)

INTERIOR ROOMS:

Floors: There are some signs of water damage to laminate flooring. This is common when water gets into seams of this flooring. Recommend gluing seams where there is more of a chance of moisture penetrations, such as at entryways, near sinks, tubs, toilets. This will help reduce damage over time.

Recommend adding additional bracing to garage rafters since it appears that one has been cut into when door opener was installed some time ago. This is a possible structural concern.

Ceilings: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

CEILINGS

Ceilings: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

KITCHEN:

Cosmetic damage at kitchen sink.

Sinks: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Faucets: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Faucets: Leaks when operated. (2)

Cabinets: Sprung / broken hinges found at one or more cabinet doors. (2)

BATHROOMS:

Sinks: No Functional / Mechanical Defects Found To Report At The Time Of Inspection. Sinks: Porcelain surface is chipped at: *** (2)

Sinks: Porcelain surface is chipped at: *** (2)

PLUMBING:

No Functional / Mechanical Defects Found To Report At The Time Of Inspection. No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Water Meter: Unable to locate the water meter. Recommend contacting the seller / water company or the property owners association to determine the location of the meter. (2)

Water Meter: Unable to locate the water meter. Recommend contacting the seller / water company or the property owners association to determine the location of the meter. (2)

ELECTRICAL:

Main Panel: The connection of two or more conductors to a single breaker, called Double Tapping, was found in the Main Panel. This condition can cause overheating / breaker malfunction / fire. Possible Safety Hazard

Main Panel: Circuit Breaker labels are missing / incomplete / Illegible.

Missing knock out plug('s) at main panel. Possible Safety Hazard

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

This report is the private property of Mr Sample Client (Do Not Copy or Reproduce.)

COMMENTS AND NOTES**Unregistered Software 1-760-650-1255****Report #: Samp070612**

Your Company Address

Client: Mr Sample Client

Tampa Florida 32569

Property: 411 Circle Caviar, Murrieta, Ca, 92562

850-737-1234 inspector@gmail.com

Inspection Date: July 12, 2012

Inspector: Inspectors Name

Part : 3

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

HEATING / COOLING

Heating / Cooling Comment: Recommend having heat and A/C serviced annually.

Heating: Small gas leak detected at furnace at main control valve. See Photo

GARAGE

Slab / Floor: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Slab / Floor: No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Slab / Floor: Typical Cracks

LAUNDRY:

No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

No Functional / Mechanical Defects Found To Report At The Time Of Inspection.

Counter Tops

Counter Tops

COMMENTS AND NOTES:**Comments**

Security Alarm System: Testing / evaluation of this system is beyond the scope of this report. (2) additions / alterations noted but not necessarily limited to the Following items / components / associated features listed below. unable to determine if any of this work was done with required permits or by qualified licensed contractors / specialty trades persons. client is strongly advised to obtain & review as complete a permit history on this property as is available prior to close of escrow.

Property Owners Association / Park Management Statement

The residential dwelling unit appears to be part of a complex that is maintained by a property owners association and / or park management. The inspection will be limited to a visual evaluation of the items, systems, components and associated features that are located within and adjacent to the dwelling unit inspected. The current condition of any "common elements" such as, but not limited to, stairs; landings; porches; hallways; balconies; decks; patios; pools; spas; recreational areas / equipment; elevators; utility metering; parking stalls / ports; building site condition; structural stability; and all common areas are not considered to be part of the inspection report. Any comments made regarding same, have been made as a courtesy only, and should be addressed to the property owners association / park management or their representative. It is suggested that the property owners association / park management operation budget, including a reserve study, be carefully reviewed. The reserve study should provide an awareness as to the anticipated remaining life expectancies of the major components and systems. The budget should also include a statement of the present funds, and a funding strategy to cover future major repair and / or replacement. Approved or anticipated special assessments should also be addressed. It is also suggested that the current property owner be consulted regarding known past defects, all corrective work performed, and to thoroughly review the "C. C. & RS" and reserve study for disclosure of any pertinent

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

This report is the privet property of Mr Sample Client Do Not Copy or Reproduce.

COMMENTS AND NOTES**Unregistered Software 1-760-650-1255****Report #: Samp070612**

Your Company Address

Client: Mr Sample Client

Tampa Florida 32569

Property: 411 Circle Caviar, Murrieta, Ca, 92562

850-737-1234 inspector@gmail.com

Inspection Date: July 12, 2012

Inspector: Inspectors Name

Part : 4

This Action List Is Only For Quick Reference And Not To Used As A Substitute For Reading The Inspection Report. I Always Recommend That All Repair Work Or Visual Examinations Be Performed By A Licensed Professional In The Related Field.

facts affecting the current condition and market value of the property, the properties common elements and areas, and any existing or pending litigation.

OTHER SYSTEMS:

Add any Appliance Comments: 00

REPORT LEGEND

- (1) Recommended evaluation by a Licensed Structural Engineer / Geo-Technical Engineer.
- (2) Recommend evaluation or repairs by a Qualified Licensed Contractor / Specialty Trades Person.
- (3) Recommend evaluation of Infestation / Deterioration by a Licensed Pest Inspector.
- (4) Recommend evaluation / testing by a Licensed / Certified Environmental Contractor / Specialist.
- (5) Recommend upgrading for Health / Safety / Function / Efficiency Enhancement.
- (6) Additions / Alterations to this item or system noted, unable to determine if this was done with any required permits or by a Qualified Licensed Contractor / Specialty Trades Person.

This report is the privet property of Mr Sample Client Do Not Copy or Reproduce.